



Your INSPECTION REPORT

Vehicle Description:

Date of Inspection: 03/16/2020

Full VIN: 5TFEY5F13KX252640

Year: 2019

Engine Cylinders: 8

Mileage: 8,982

Make: Toyota

Engine Liters: 5.7L

Transmission Type: Automatic

Model: Tundra SR5 Engine Type: Gas

Inspection Area	Overall Rating
Body	Excellent
Glass	Excellent
Wipers	Excellent
Tires & Wheels	Good
Interior Items	Excellent
Gauges	Excellent
Audio System	Excellent
Carpet & Upholstery	Excellent
Trunk	Excellent
Electrical System	Excellent
Under Hood	Excellent
Road Test	Excellent
Additional Inspection Points	Excellent



Exterior

BODY OVERALL RATING: EXCELLENT

Front	OK	Rear	OK
Hood	OK	Roof	OK
Bumpers	OK	Trim	OK
Left front	OK	Right front	OK
Left rear	OK	Right rear	OK
Left doors	OK	Right doors	OK
Overall Condition of Paint	EXCELLENT		

GLASS OVERALL RATING: EXCELLENT

Windshield	OK	Rear window	OK
Left front window	OK	Right front window	OK

Left rear window	OK	Right rear window	OK
------------------	----	-------------------	----

TIRES AND WHEELS **OVERALL RATING: GOOD**

Condition of tires	EXCELLENT	Condition of wheels	GOOD
--------------------	-----------	---------------------	------

Comments on Tires and Wheels:

N/A

WIPERS **OVERALL RATING: EXCELLENT**

Front wipers	OK
Front wiper blades	OK
Front windshield washer	OK

Comments on Exterior:

THE BODY AND PAINT ARE IN EXCELLENT CONDITION. THE BODY IS DING AND DENT FREE. ALL BODY PANELS ARE ALIGNED.

Interior

INTERIOR ITEMS **OVERALL RATING: EXCELLENT**

Glove box	OK	Head rests	OK
A/C cooling performance	OK	Door panels	OK
Heater operation	OK	Dash pad	OK
Hood release	OK	Vanity mirrors	OK
Cigarette lighter	OK		

GAUGES **OVERALL RATING: EXCELLENT**

Speedometer	OK	Oil pressure	OK
Tachometer	OK	Amp meter	OK
Temperature	OK		

AUDIO SYSTEM **OVERALL RATING: EXCELLENT**

Radio	OK
Tape player	OK
CD player	OK

CARPET AND UPHOLSTERY **OVERALL RATING: EXCELLENT**

Front seats	OK	Rear seats	OK
Front carpeting	OK	Rear carpeting	OK

Headliner	OK
-----------	----

TRUNK **OVERALL RATING: EXCELLENT**

Carpeting	OK	Spare tire	OK
Tools	OK	Floor pan	OK
Jack	OK		

ELECTRICAL SYSTEM **OVERALL RATING: EXCELLENT**

Head lights	OK	Turn signals	OK
Tail lights	OK	Electric windows	OK
Brake lights	OK	Electric seats	OK
Parking lights	OK		

Comments on Electrical System:

ALL POWER ACCESSORIES WERE OPERATIONAL.

UNDER THE HOOD **OVERALL RATING: EXCELLENT**

Oil leaks	NO
Exhaust leaks	NO
Exhaust smoke	NO

Comments on Interior:

THE INTERIOR IS VERY CLEAN AND SHOWS LITTLE OR NO WEAR.

Road Test

ROAD TEST **OVERALL RATING: EXCELLENT**

Brake system - noise, vibration, effort	OK	Steering effort - drifting right or left	OK
Suspension - performance, noise, rough road test	OK	Transmission shift quality, smoothness, effort, slippage	OK
Idle	OK	Engine operating temperature	OK
Engine noise	OK	Transmission/Transaxle noise	OK
Acceleration	OK	CV joint/Drive axle noise	OK
Horn	OK	Parking brake operation	OK
Wind noise	OK	Engine performance	OK
Starting	OK		

Comments on Road Test:

THE ENGINE WAS QUIET,SMOOTH,AND RESPONSIVE. THE TRANSMISSION SHIFTED SMOOTHLY. THE BRAKES AND STEERING PERFORMED WELL WITH NO NOISE OR VIBRATION. OVER ALL ROAD SURFACES VEHICLE WAS QUIET AND RATTLE FREE. THERE ARE NO APPARENT MECHANICAL ISSUES.

Additional Inspection Points

ADDITIONAL INSPECTION POINTS		OVERALL RATING: EXCELLENT	
Rooftop	OK	Door locks	OK
Door handles	OK	Keyless entry	OK
Gas door	OK	Gas cap	OK
Grille	OK	Fog lamps	OK
		Evidence of smoke odor	OK

Comments on Additional Inspection Points:

N/A